


Polarity Reversal Mode Simple


- Efficient management of dual cables
- Simple Reversible of polarity process - no jig required
- Outstanding laser and dust protection
- Compact design

1




1. Turn the Uniboot over

2




2. Unlock the nail

3



3. Take off the latch


4



4. Place back the latch on the "R" side


LC Uniboot Polarity Reversible Connectors Direct and Crossed Modes:

Blank to Blank - **Crossed**



When the latch is connected on the blank side on both sides of the patch cord, the patch cord is **Crossed**

"R" to Blank - **Direct**



When the latch is connected on the blank side in one side of the patch cord & on the "R" side on the other side of the patch cord is **Direct**